

INDEX

Symbols

9-pin motor
Color code 17

A

AC Power Connection 27
AC power connection
Molded power cable 27
Amps
Current ratings 29
Applications Engineering Department
54
Assumptions vii
Automatic standby function 49
Automatic test function 5, 49

B

Best performance 1
Bipolar
Current 22
Output type 39

C

Cabinet loss 29
CE 55
CE Mark ii
Product Type ii
Color code 13
Series and Parallel 14, 15, 16
Color codes
9-pin motor 17
Common problems and solutions 53
Compumotor
Applications Engineering 32
Motors
9-pin version 17
S106-205 15
S106-250 16

Contents of this manual vii
Core losses 29
Coupling manufacturers 33
Couplings 33
Shaft couplings 33
Current
Bipolar 22
Current (Amps)
Current rating 29

D

Developing Your Application viii
DIP switch
Summary 47
DIP switch settings
Automatic Standby 24
Automatic Test 5, 25
Drive configuration 24
Motor current 18
Motor current settings 18
Motor resolution settings 24
Motor waveforms 25
Quick-reference tool 39
DIP switches 4, 11
Location 4
Modification 11
S6 Motor Current 5
S8 Motor Current 5
SW1 4, 11
SW1-#3 4, 11
SW2 4, 11
SW2-#3 4, 11
Direction input 40
Double-Flex Coupling 33
Drive configuration 24
Drive label 3
Drive maintenance 51
Drive temperature 39
Drive/Indexer Connection 26

E

Electrical noise 10
Electrical specifications 39
Input power 39
Output power 39
Environmental considerations 9
Environmental specifications 39
Extended Motor Cables 18

F

Failed drive 54
Returning the system 54
Fan connection 27
Fan kit 27
Fault input 40
Fault output 27, 39
Schematic 26
Features 1
Filter 10
Fine tuning 36
Front panel LEDs 52

G

Gauging motor resonance 35
Getting started 3
Grounding 10
Motor casing 10
Requirements 10
Temporary installation 10

H

Hardware reference 39
Heatsink temperature 9
High-power 48
How to use this User Guide i, vii
Hyperbola 30

I

- Indexers 37
 - Equations 37
 - Linear resolution 37
 - Rotary resolution 37
- Input
 - Direction input 40
 - Fault input 40
 - Set Zero Phase Input 40
 - Shutdown & Set Zero Phase Signal
 - Specification 40
 - Shutdown input 40
 - Step pulse input 40
- Input power 39
- Inputs 26
 - Direction input 26
 - Schematic 26
 - Shutdown Input 26
 - Step & Direction Signal
 - Specification 40
 - Step pulse input 26
- Installation 9
 - Precautions 9
- Installation overview 12
- Installation Preparation viii
- Installation Process Overview viii
- Internal thermostat 9
- Introduction 1
 - Features
 - Product description 1
- Isolation transformer 28

L

- LEDs 52
 - Motor Fault LED 52
 - Overtemp LED 52
 - Power LED 52
 - Step LED 52
 - Undervoltage LED 52
- Load 33
- Low-power 48
- LVD
 - Electrical 55
 - Environmental conditions 55
 - Graphics table 57
 - Installation instructions ii, 55
 - Line fuses 56
 - Mechanical 56
 - Protective earth connection 56
 - Servicing the S Drive 56
 - Sonic pressure 57
 - Thermal safety 57
- LVD Compliance 55

M

- Maintenance 51
- Malfunctioning
 - Testing the motor 54
- Maximum motor wiring inductance 40
- Mid-range instability 34
- Minimum motor wiring inductance 39
- Misalignments 33
- Molded power cable 27
- Motor
 - Performance specifications
 - Motor windings 49
 - Resolutions 24, 49
 - Motor configuration 13
 - Motor current 4, 47
 - DIP switch table 4
 - S6 drive motor 18
 - S8 drive motor 18
 - Motor heating 13
 - Motor maintenance 51
 - Motor mounting 32
 - Flange bolts 32
 - Motor performance specifications 49
 - Motor temperature 39
 - Motor type 29
 - Motor waveforms 36, 49
- Motors
 - Motor cables 18, 22
 - NEMA 23 Motor Dimensions 43
 - NEMA 34 Motor Dimensions 45
 - S106-205 Motor Dimensions 46
- Mounting 31
 - Clearance 32
 - Minimum depth 31
 - Minimum width 31
- Mounting clips
 - Screws 31

N

- Non-Compumotor motor
 - Caution 19
 - Pre-wired motor cable 5
- Non-Compumotor motors 5
 - Bipolar current 22
 - Motor current
 - High-power S8 Drive 23
 - Low-power S6 Drive 23
 - Precautions and instructions 5
 - Recommended motor cables 22
 - Requirements 19
 - Setting motor current 22
 - Terminal connections 21
 - Unipolar current 22
 - Wiring configurations 19
 - 4-Lead Motor 19
 - 6-Lead Motor 19
 - 8-Lead Motor 20

O

- Ohmmeter 19
- Operational specifications
 - Accuracy 41
 - Repeatability 41
- Operational specificationsSpeci 41
- Output power 39

P

- Panel layout
 - Guidelines 32
- Parallel configuration 20
- Parametric oscillations 34
- Peak Motor Loss 29
- Peak Shaft Power 30
- Peak Total Power 30
- Phase A Offset 34
- Phase B Offset 34
- Phase balance 34
- Power cable 6
- Pre-wired motor cable 5
- Precautions 9
- Product description 1

Q

- Quick Test 3
 - DIP switches 4
 - Indexer 6

R

- Related Publications viii
- Repair 54
- Resonance 34
- Resonance speed 35
 - Method 35
- Return Material Authorization (RMA) 54
- Rigid Coupling 33

S

- S Drive 3, 18
 - Damage report 3
 - DIP switch summary 47
 - high-power 3, 18
 - Limited voltage 27
 - low-power 3, 18
 - Microstepping capability 34
 - Power ratings 28
- S6 Drive
 - Fan kit 29
 - Low-power 48
 - Motor current setting 48
- S8 Drive
 - High-power 48
- Series configuration 20
- Series vs. Parallel Wiring 13
- Set Zero Phase Input 27, 40
- Shaft couplings 33
- Ship kit 3
- Shutdown & Set Zero Phase Signal
 - Specification 26, 40
- Shutdown input 7, 30, 40
- Single-Flex Coupling 33
- Spare parts list 51
- Step & Direction Signal Specification
 - 26, 40
- Step pulse input 40
- Step pulses 7, 30
 - Shutdown input 30

T

- Testing the motor 54
 - Malfunctioning 54
- Thermal dissipation 29
- Thermal interface 10
- Transformer specifications 28
 - Table 28
- Troubleshooting 51
 - Maintenance 51
- Tuning 34
 - Potentiometers 34
 - Tuning procedures 34
- Tuning Procedures 34

U

- User Guide Change Summary i

V

- Volt-Amp
 - Rating 30

W

- Warning 12
- Waveform
 - Correct motor waveforms 36
- Waveform Symmetry DIP switches
 - 36
- Winding inductance 39
- Wiring considerations 9
 - Guidelines 9
- Wiring diagram 12

